



**G112 Central flap motor position sensor**

- on bottom of heater box, forward of footwell outlet duct
- integral with flap motor –V70–