



G56 Instrument panel interior temperature sensor

- in central console, below radio
- integral with –E87–, –V42– and –J255–